

**Product information**

Further products in category:  
 Engine | **Electrical**  
 Engine | **Exhaust**

**Tester for E-positioner VAS 6395A**

The testing device VAS 6395A is required for replacement of E-positioners (servomotors) on the turbocharger. With VAS 6395A, the old servomotors can be interrogated and readjusted with the aid of a step-by-step guide. Since the new servomotors have to be adjusted precisely to 20 mV, an exchange without VAS 6395/6395A is not possible. The application is described in the workshop manual.

Initial introduction: Audi A4 and Audi A6, with 2.7 L and 3.0 L TDI engine.

**Items supplied**

E-Box VAS 6395A/1, ASE 404 571 01 000;

Connection cable 2,7l TDI or HELLA servo VAS 6395/2 (2.7 L TDI with exhaust emissions standard EU4, EU5, EU6 and 3.0 L TDI with exhaust emissions standard EU5, EU6 and BIN5), ASE 404 572 00 000;

Bracket VAS 6395/3 (2.7 L TDI with exhaust emissions standard EU4 and EU5), ASE 404 573 00 000;

Storage case VAS 6395/9, ASE 404 579 00 000;

**Recommended accessories**

Bracket (Q7, A4 and A5 with 2.7 L and 3.0 L TDI with exhaust emissions standard EU6 and BIN5)  
 VAS 6395/5, ASE 404 578 00 000

Bracket

VAS 6395/6, ASE 404 580 00 000

Supplementary set for Siemens VDO E-positioner

VAS 6395/4, ASE 404 574 00 000

Comprising:

Update cable (only required in conjunction with previous model VAS 6395)

VAS 6395/4-1; ASE 404 575 00 000

Connection cable (servos on intake manifold flaps 2.7 L and 3.0 L TDI with exhaust emissions standard EU4 and servos on turbocharger 3.0 L TDI with exhaust emissions standard EU4)

VAS 6395/4-2; ASE 404 576 00 000

Open end spanner

VAS 6395/4-3; ASE 404 577 00 000

**Warranty**

24 months

**Manufacturer**

Omitec Deutschland GmbH, Frankfurt

**ASE 404 570 01 000**